Approved Fo	or Reterse 2002	2/10/25st;C	A-ROB	5 B0028	5R000200	120003-4 20003	65 Harmonistani
	The state of the s					DM 9	ta kabasitatista sipraati oli ohapoist Balainin saki kali ohee siiki sitoista saki siki sitoista saki saki siki saki sitoista saki saki siki saki saki saki saki sak
TE LONGER STEERING ON STREET WAS THE CHAPT.		Al September 1 - May resident and May 1 - Ma	THE COLOR OF THE STREET STREET, STREET STREET, STREET STREET,	ntel eff exchange to enquay to	6 6 7	Intell 13 14 14 16	Region Comment communication of address of the control of the cont
					A TOTAL PROPERTY OF THE PROPER	in in the state of	
92956			٥s	A L	in this area. Eco 1880		
E C R E T 0204	mro 32Z CITE	Banker Michael (1964) -	erm Allen eine er stern Afrikaanske fan Stern Allen en Stern Allen	The second secon	Committee Commit	OTE III	25X1
IDEALI	ST AVION			j L		D 3 E.S	25X1A
4.	92956 ECRET 0204	92956	SE 92956 ECRET 020432Z CITE	SECRE 1 92956 OS ECRET 020432Z CITE	SECRET 92956 OSA 1 ECRET 020432Z CITE	SECRET 2 3 5 6 7 8 6 7 8 9 9 2 9 5 6	Approved For Reference 2002/10/253 CIA-RIRES 5800285R002200120003 - ROUTING SECRET 1

- 1. RE PARA 3. TCG DEFINITELY ON TAPE AND INTERMITIENT AS PREVIOUSLY STATED. APPEARS PROBLEM WAS DUE BAD PLAYBACK AMPLIFIER AT _____ STEPS WILL BE TAKEN ENSURE THIS DOES NOT OCCUR AGAIN.
- 2. RE PARA 5. HAVE NO DEFINITE SUGGESTIONS, AS STATED TCG WILL NORMALLY SUFFICE.
- 3. P-BAND ALSO LOCATED HOWEVER, RECORDED ON TRACK OTHER THAN TRACK INDICATED.
- 4. SIGNAL LEVELS ALL APPEAR VERY GOOD WITH LITTLE SATURATION ENCOUNTERED. AS PREVIOUSLY STATED RECORDED SIGNALS MUCH BETTER THAN WHEN B UNIT USED.

S E C R E T TOR: 02/0502Z DEC 66

25X1A